

Oak Ridge National Laboratory Central Campus Cleanup


2011 Oak Ridge Reservation
Emergency Management
Forum

Dirk Van Hoesen
Director
EM Program Office

September 8, 2011



ORNL Central Campus Cleanup



Ruptured gas cylinder



Small gas cylinder at Bldg 3592 sheared on 5/11/2011 releasing small amount of Sulfur Dioxide - EOC was activated



Stack Emergency Response preparation



Training for ORNL
Emergency Responders
conducted in February to
support 2061 stack
demolition and 3039 stack
inspection

